

Michael F. Del Casino

Regulatory Division Manager

Suite 1000 1120 20th Street, N.W. Washington, DC 20036 202 457-2023 FAX 202 457-2165

September 1, 2000

Mr. Dale Hatfield Chief, Office of Engineering and Technology Federal Communications Commission 2000 M Street NW, Suite 480 Washington, DC 20554

Dear Mr. Hatfield:

As required by Part 63.100(a) of the Federal Communications Commission's Rules, AT&T hereby files its Final Service Disruption Report for an AT&T network outage.

1. Date / Incident Location Time:

August 2, 2000 12:46 PM EDT

2. GEOGRAPHICAL AREA AFFECTED:

Rockdale, GA

3. CUSTOMERS AFFECTED (APPROXIMATELY):

60,049 (based on blocked calls)

4. Types of Services Affected:

Toll Access, Toll Completing and International

5. **DURATION OF OUTAGE:**

3 Hours and 44 Minutes



6. BLOCKED CALLS:

180,146

7A. CAUSE OF INCIDENT:

While performing a digging operation to install a sewer line, a contractor destroyed an underground "pull-box" and consequently severed an AT&T cable. The contractor had notified the One-Call center, however the AT&T Cable Hazard Center auto-scan ticketing system determined that AT&T was not involved.

7B. EQUIPMENT NAME / TYPE:

Fiber Optic Cable

7C. PART OF NETWORK:

Atlanta, GA - Monticello, GA

8. RESTORATION METHODS:

- 419 T3s restored by FASTAR within 20 minutes
 - 51 T3s restored manually within 47 minutes
- 22 T3s restored either by manual patch or physical repair within 3 hours and 44 minutes

9. Steps to Prevent Reoccurrence:

The mapping data in the Plant Protection System (PPS) had the address range for the cable buffer in the 1100 block, when in fact the cable was in the 1200 block. The PPS buffer has been expanded to include the 1200 block address of this incident. This will ensure that the auto-scan feature will deliver a ticket to the field for appropriate handling along this route in the future.

10. APPLICABLE BEST PRACTICES:

AT&T has reviewed the <u>Network Reliability: A Report to the Nation, June 1993</u> and has evaluated all best practices in SECTION A – FIBER OPTIC CABLE DIG-UPS: CAUSES AND CURES. The following countermeasures are the most appropriate for bringing about reductions in fiber cable dig-ups.

6.1.3 Details - Key lessons and best practices

Accurate Locates – expand locate personnel training and skill levels, quality control all work.

Technical Supervision – assign technical personnel to observe activities at work sites where digging is underway.

Training – continuous refresher training and adherence to standards and procedures, train personnel to recognize conditions potentially hazardous to fiber optic cable.

Sincerely,

00-120

This form should be sent for the following timeframes: B/C 90,000-149,999 3 days B/C 150,000 & greater 120 minutes

TATA Initial Service Disruption Report

FAX TO: FCC WATCH OFFICE, WASHINGTON, DC

202-632-6975 Voice 202-418-2812 FAX

ALTERNATE FCC WATCH OFFICER

202-418-2813 FAX

| 1. Date/Time of Incident | 812100 at 12:46 ET |
|--|--------------------------------|
| 2. Geographic Area Affected | Atlanta, 64 - Orlando, M |
| 3. Customers Affected (est) | 30,000 ± |
| 4. Types of Service Affected | toliconnect |
| 5. Duration of Outage | shill facked at time of report |
| 6. Blocked Calls (est) | 96,000 + |
| 7A, Cause of Incident | Contractor Calole Cut |
| 7B. Equipment Name/Types | FIBER OPTIC CABLE |
| 7C. Part of Network Affected | Atlanta GA - Oilardo, FL |
| 8. Restoration Methods Used | NIX |
| 9. Steps to prevent recurrences | MIA |
| | |
| AT&T Contact Person: Telephone Number: Date/Time of Report | 202-457-2023 |
| | |